

Annexure-D
BUILDING SAFETY CERTIFICATE

No-

Date-31.08.2026

It is Certified that the existing building Pandit Rampal Smirti Public School Manpur (name of the building or premises) at Beohari road ward no. 05 Manpur (address) is having blocks (s) /Floor(s) as per details below.

Details of Block(s) in school	Block No.01	Block No.02	Block No.03	Block No.04	Block No.05	Block No.06
No. of floor(s) in the Block	2					

The building is owned /occupied by Pandit Rampal Smirti Public School Manpur (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules , and verified by the officers concerned of Housing And Urban Development (Name of Department /Govt.) on 16.09.2026 (date of inspection) in the presence of Suman Dwivedi (Manager) Ward no.01 Subhash colony Manpur (name and addresses of the Manager /Secretary or his representative) and that the building /premises is fit for occupancy for running school with effect from 16.09.2026 For a period of 15 Years in accordance with rule and subject to compliance of the specific conditions on appended.

- 1.
- 2.
- 3.
- 4.

Issued on 16.09.2026 at Manpur by

Strike out whichever is not applicable in case of block is more than six use separate sheet for details.

Signature with Seal:-

Name- Shalini Tripathi

Designation with office

Name & Address Of Department /Office -

Ward no.01 Semra Manpur

Tahsil Manpur District Umari Mp

